



JON M. HUNTSMAN, JR.
Governor

GARY R. HERBERT
Lieutenant Governor

State of Utah

DEPARTMENT OF NATURAL RESOURCES

MICHAEL R. STYLER
Executive Director

Division of Oil, Gas and Mining

JOHN R. BAZA
Division Director

September 15, 2008

Kenneth E. May, General Manager
Canyon Fuel Company, LLC.
P.O. Box 1240
Huntington, Utah 84528

Subject: Rejection of Permit Amendment, Tipple Sump, Task ID #3040, Canyon Fuel Company, LLC, SUFCO Mine, C/041/0002

Dear Mr. May:

The Division received your application for the above-noted permit change on August 28, 2008. Pursuant to R645-303-221, the Division completed the requisite Initial Review (IR) and denies this application for a technical review based on the following deficient materials.

1) There is no written description of the structure in the MRP. 2) There are three different names for the structure in the material submitted. 3) The name of the structure is not distinguished from the sediment trap below the truck scale. 4) All maps should reflect the same name of the structure. 5) The purpose of the structure is not stated. 6) Information describing all surface facilities should be identified in Chapter 5 (Engineering), Sections 5.1.2.2, 5.1.3.2 and in the Operation Section 5.2.1.1. 7) The structure should be identified in Table 5-4 (Description of Existing Structures) and in the Demolition Costs table. Information should be provided in Section 5.2.1.1 that details any influence on the surface runoff conditions. 8) Any influence should be identified in the Surface Hydrology section in Chapter 7.

If you have any questions, please call David Darby at (801) 538-5341 for further details.

Sincerely,

A handwritten signature in black ink, appearing to read "J. Smith".

James Smith
Permit Supervisor

an

cc: Price Field Office

O:\041002.CON\FINAL\ICRrejectionTippleSump91508.doc

